				<del></del>	1
Err	0	0	0	0	0
. =					
Err r D finiti					
C m m nt					
Tim Stamp	2003/03/12 12:48	2003/03/12 12:49	2003/03/12 12:49	2003/03/12 13:12	2003/03/12 13:12
DBs	PGPUB;	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB
S arch T xt	compressor and compre	1 and ((crank or crankshaft) with (channel or bore or passage or groove))	2 and rod	3 and bearing	4 not swash
Hits	1869	741	380	314	224
L #	7	2	2	:	ਨ
Тур	BRS	BRS	BRS	BRS L4	BRS
	<del>-</del>	N	m	4	ro